QUESTIONS & ANSWERS

Kill your exam at first Attempt

Nortel

922-095

Communication Server 1000E Rls.5.0 Install and Commissioning

A. The transfer status of the node is in progress.
B. The node configuration is transferred to the elements.
C. The transfer status of the node elements is unavailable.
D. An element within the node failed to transfer the BOOTP or CONFIG files.

Answer: C

QUESTION: 23
Upon opening the web browser to begin the login process into Element Manager on a Communication Server (CS) 1000E system, which two IP addresses can you enter into the address bar of the web browser? (Choose two.)

A. the Call Server IP address
B. the Signaling Server Node IP address
C. the Terminal Proxy Server (TPS) IP address
D. the Embedded LAN (ELAN) IP address of the Signaling Sever

Answer: B, D

QUESTION: 24
A customer has successfully installed and configured a Signaling Server in a Communication Server (CS) 1000E system. After configuration and reboot, the Follower Signaling Server sends out BOOTP requests and waits for a response. However, there is no BOOTP response. Which action should be taken?

A. Reboot the Leader Signaling Server.
B. Wait for a BOOTP response from the Leader Signaling Server.
C. Configure the IP Telephony node for the Follower from Element Manager.
D. Configure the IP Telephony node for the Follower from the Installation Tools menu.

Answer: C

QUESTION: 25
You have completed installing a Communication Server (CS) 1000E CP-PIV system. The system has been operating in normal conditions. One day, the lab temperature rises and causes the alarm/fan module temperature in the CP-PIV Call Server to exceed 60 degrees Celsius. What impact does this have on the system?

A. A major alarm is triggered.
B. The health of the active Call Server decreases.
C. The Call Server Fan units switch into high-speed.
D. The Call Server switches to the standby Call Server.

Answer: A

Kill your exam at First Attempt....Guaranteed!